

Two speed motor starter Two separate windings
(constant NEMA size 0 3-Phase, 3Pole Maximum
voltage rating 600VAC Max Hp 60Hz: 2@200V;
2@230V; 3@460V; 3@575V Solid-state overload relays
Control voltage 110VAC 50Hz / 1 Open device (no
enclosure)

Further information

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.de/industrial-controls/catalogs>

Industry Mall (Online ordering system)

<https://mall.industry.siemens.com>