



Representative Image

Alternate Catalog No. OTPL60FP**Catalog No. 1SCA111004R1001****Description: LATE BREAK EARLY MAKE POLE****UPC No 6417019441733****Home > Switches & Disconnects > Disconnect & Safety Switches > Disconnect Switches > Rotary Disconnects**

OTPL60FP Fourth pole with late-break and early make function. Mountable on the side of the switch.

Descriptors

Category

Rotary Disconnects

Specifications

Product Name	Accessories
Accessory Type	Fourth pole/Neutral
Accessory Sub Type	FOURTH POLE
Product Main Type	OTPL60
Suitable For	OTM40
Quantity / Count	1